

Chris Rauwendaal

# SPC

## Statistical Process Control in Injection Molding and Extrusion

2nd edition

HANSER

Hanser Publishers, Munich • Hanser Gardner Publications, Cincinnati

# Contents

<b>1</b>	<b>Injection Molding Technology</b>	<b>1</b>
1.1	The Main Components of an Injection Molding Machine	1
1.1.1	The Injection Molding Cycle	2
1.1.1.1	Characteristics of the Injection Molding Process	4
1.1.2	The Plasticating Unit	5
1.1.2.1	The Extruder Screw	5
1.1.2.2	Nonreturn or Check Valves	6
1.1.2.3	The Extruder Barrel	8
1.1.2.4	The Nozzle of the Plasticating Unit	8
1.1.2.5	The Feed Hopper and Feed Opening	10
1.1.2.6	The Extruder Drive	10
1.2	The Clamping Unit	11
1.2.1	Mechanical Clamping Systems	12
1.2.2	Hydraulic Clamping Systems	13
1.2.3	Hydromechanical Clamping Systems	14
1.3	The Mold	14
1.3.1	The Sprue	15
1.3.2	The Runner System	16
1.3.2.1	Cold Runner Systems	16
1.3.2.2	Balancing the Runner System	18
1.3.2.3	Cold Slug Traps	19
1.3.2.4	Gates	19
1.3.2.5	Hot Runner Systems	20
1.3.3	Flow into the Mold	22
1.3.3.1	Venting	24
1.3.3.2	Weld Lines	25
1.3.3.3	Mold Filling Analysis	26
<b>2</b>	<b>Extrusion Technology</b>	<b>27</b>
2.1	Introduction	27
2.2	The Functions of an Extruder	29
2.2.1	Conveying	29
2.2.2	Heating and Melting	32
2.2.3	Mixing	34
2.2.3.1	Distributive Mixing	36
2.2.3.2	Dispersive Mixing	36
2.2.4	Die Forming	37
2.2.4.1	Guidelines for Shapes	39

---

2.2.4.2	Guidelines for Die Design .....	39
2.2.5	Devolatilization or Degassing .....	40
2.3	Efficient Extrusion .....	41
2.3.1	Efficient Machine Design .....	41
2.3.1.1	The Extruder Screw .....	42
2.3.1.2	The Extruder Barrel .....	43
2.3.1.3	The Feed Hopper and Throat .....	44
2.3.1.4	The Extruder Drive .....	46
2.3.1.5	Instrumentation and Control .....	46
2.3.2	Efficient Process Operation .....	47
2.3.2.1	Feed Stock Consistency .....	47
2.3.2.2	Temperatures .....	48
2.3.2.3	Screen Pack .....	49
2.3.2.4	Feeding .....	50
2.3.2.5	Gear Pumps .....	51
<b>3</b>	<b>Plastics and Plastics Properties Important in Injection Molding and Extrusion</b> .....	<b>53</b>
3.1	Thermoplastics and Thermosets .....	53
3.2	Amorphous and Semicrystalline Plastics .....	53
3.3	Liquid Crystalline Plastics .....	54
3.4	Elastomers .....	55
3.5	Flow Behavior of Plastics .....	55
3.5.1	The Melt Index Test .....	56
3.5.2	Spiral Length Tester .....	57
3.5.3	The Effect of Shearing .....	57
3.5.3.1	Shear Thinning or Pseudoplastic Behavior .....	58
3.5.3.2	Effect of Temperature on Viscosity .....	59
3.5.3.3	Effect of Pressure on Viscosity .....	59
3.5.4	Flow Properties for Injection Molding .....	59
3.5.5	Viscous Heat Generation .....	60
3.6	Thermal Properties .....	60
3.6.1	Thermal Conductivity .....	61
3.6.2	Specific Heat and Enthalpy .....	61
3.6.3	Thermal Stability and Induction Time .....	62
3.6.4	Density .....	62
<b>4</b>	<b>Introduction to Statistical Process Control</b> .....	<b>65</b>
4.1	Introduction .....	65
4.2	Implementing Statistical Process Control .....	68
4.3	Basic Statistical Concepts .....	73
4.3.1	Causes of Variability .....	73
4.3.2	Basic Statistical Terms .....	75

4.3.3	Mean, Median, and Mode .....	75
4.3.4	Range, Variance, and Standard Deviation .....	76
4.3.5	Plotting Distribution Patterns .....	78
4.3.6	Characteristics of a Frequency Distribution .....	82
4.3.7	Different Distribution Patterns .....	83
4.3.8	The Central Limit Theorem .....	84
<b>5</b>	<b>Data Collection, Data Analysis, and Problem Solving .....</b>	<b>87</b>
5.1	Attributes Data Versus Variables Data .....	87
5.2	Important Aspects of Data Collection .....	87
5.3	Diagrams for Problem Solving .....	88
5.3.1	Cause Listing Diagram .....	88
5.3.2	Variation Analysis Diagram .....	89
5.3.3	Process Analysis Diagram .....	90
5.4	Pareto Diagrams .....	91
5.5	Histograms .....	93
5.6	Scatter Diagrams and Correlation Tables .....	93
5.7	Recording Data .....	95
5.7.1	Check Sheets .....	95
5.7.2	Portable Data Collectors/Machine Analyzers .....	97
5.7.3	Fixed Station Data Acquisition Systems .....	98
5.8	Sampling .....	101
<b>6</b>	<b>Measurement .....</b>	<b>103</b>
6.1	Introduction .....	103
6.2	Basic Concepts .....	104
6.3	Measurement Error .....	106
6.4	Quantifying Measurement Variation .....	107
6.4.1	Short Method for Gage R&R .....	109
6.4.2	Long Method for Gage R&R .....	110
6.4.3	Gage Accuracy .....	113
6.4.4	Gage Stability .....	113
6.4.5	Gage Linearity .....	114
6.4.5.1	Guidelines .....	114
6.5	Graphical Method for Measurement Analysis .....	114
6.5.1	Traditional Gage R&R Method .....	115
6.5.2	Graphical Approach to Gage R&R .....	116
6.5.3	Differences Between Operators .....	118
6.5.3.1	Measurement Error and Product Variation .....	118
6.6	Measurements in Injection Molding .....	120
6.6.1	Important Process Parameters .....	120
6.6.1.1	Product Characteristics .....	121

---

6.6.1.2	Pressure .....	121
6.6.1.3	Temperature .....	124
6.6.1.4	Screw Speed .....	126
6.7	Measurements in Extrusion .....	126
6.7.1	Important Process Parameters .....	126
6.7.1.1	Extrudate Dimensions .....	127
6.7.1.2	Pressure .....	127
6.7.1.3	Screw and Take-Up Speed .....	129
7	<b>Control Charts</b> .....	131
7.1	Introduction .....	131
7.2	Control Charts for Variables Data .....	131
7.2.1	The $\bar{x}$ and $R$ Chart .....	132
7.3	Interpretation of $\bar{x}$ and $R$ Charts .....	137
7.4	Control Charts for Attributes Data .....	140
7.4.1	Creating and Analyzing Attributes Control Charts .....	141
7.4.2	The $p$ Chart .....	141
7.4.3	The $np$ Chart .....	144
7.4.4	The $c$ Chart .....	146
7.4.5	The $u$ Chart .....	147
8	<b>Process Capability and Special SPC Techniques for Molding and Extrusion</b> .....	151
8.1	Introduction .....	151
8.2	Capability Indices .....	152
8.2.1	Process Capability Shortcut with Precontrol .....	154
8.3	Tests for Normality .....	155
8.3.1	Graphical Methods .....	155
8.3.2	Statistical Calculations .....	157
8.4	Capability Measures for Non-Normal Distributions .....	159
8.5	Special SPC Techniques for Injection Molding .....	161
8.5.1	Family Processes .....	161
8.5.1.1	Median/Individual Measurement Control Charts .....	162
8.5.1.2	Group Charting .....	164
8.5.2	Grading Machine Capability .....	165
8.6	Example of SPC in Extrusion .....	167
8.6.1	Introduction .....	167
8.6.2	Specific Example Overview .....	168
8.6.3	Low Cost Portable SPC Package .....	169
8.6.4	The Extrusion Line .....	170
8.6.5	Extrusion Line Changes, General .....	171
8.6.6	Extrusion Line Changes, Details .....	172
8.6.7	Conclusions .....	173

<b>9 Other Tools to Improve Process Control</b>	175
9.1 Introduction	175
9.2 Design of Experiments (DOE)	176
9.3 The Shainin Methodology	177
9.3.1 Tools to Generate Clues	179
9.3.1.1 Multi-Vari Charts	179
9.3.1.2 Components Search	180
9.3.1.3 Paired Comparisons	182
9.3.1.4 Variables Search	182
9.3.2 Factorial Designs	184
9.3.2.1 Interaction	185
9.3.2.2 Two-Level Factorial Design with $K$ Factors	187
9.3.3 The $B$ Versus $C$ Analysis	188
9.3.4 Scatter Plots to Determine Appropriate Tolerances	192
9.4 Precontrol	194
9.4.1 Comparing Precontrol to Control Charts	196
References	199
Appendix I, List of Polymer Acronyms	203
Appendix II, Nomenclature	213
Appendix III, SPC/DOE Software	215
Appendix IV, Expressions for the Normal Distribution Curve and $z$ -Table	223
Appendix V, Glossary	227
Appendix VI, Monitoring Systems for Injection Molding	235
Appendix VII, Conversion Constants	237
Appendix VIII, List of Acronyms	241
Appendix IX, Proposed New Terminology	243
Subject Index	245